

Alternator Decision:

Starter Decision:

VEHICLE SUMMARY

VIN: 5FRYD4H26FB010884 **Assembly Factory:** HONDA MANUFACTURING OF

ALABAMA

Make: **ACURA** BLACK PREM - BK (A) **Factory Interior Color:**

ALABASTER SILVER METALLIC Model: MDX **Factory Exterior Color:**

Model Year: 2015 **Destination Code:**

Trim: **AWDMDX** Retail Sales Date: 09/23/2014

Transmission: 6AT Retail Dealer Name: ACURA OF SERRAMONTE

Engine: 6 **Retail Dealer Phone:** 6509851000 52079

Door Qty: 5 Last Reported Mileage:

Battery Management Information System (1) Service Date: 07/22/2017 **BATTERY TEST SERVICE INFORMATION Dealer Number:** 251154 Tech ID: JONATHAN Service Date: **Tool Stock Number:** 07/22/2017 Service Time: 2:05 PM **Tool Serial Number:** 0812330193 Service Type: **BATTERY TEST** Tool Type: ED18V3 **BATTERY INFORMATION** Amp-hour: 0 Charge Time: **Battery Temperature:** Initial Voltage: 0 100 Initial Measured Capacity: Temperature Units: F 12.53 **Battery Location:** IN VEHICLE Voltage: Cold Cranking Amps(CCA): Vehicle Status: 861 **Customer Owned** Rated CCA: 610 **Battery Type: FLOODED SERVICE RESULTS Battery Decision: GOOD BATTERY Battery Test Code:** AQU3S-N1WJR

Alternator Test Code:

Starter Test Code:

Campaign (2)	Campaign information is display	Campaign information is displayed for the last 15 years; older campaigns may not be included.			
M49: 2014-19 MDX Tail Recall	gate Inner Taillight Safety	Active Date: 03/29/2019	Campaign CLOSED		
CAMPAIGN INFORMATIO	N				
Campaign Name:	MDX Tailgate Lid Light Electrical Short Safety Recall	Campaign Type Description:	Recall		
SUB-CAMPAIGN INFORM	ATION				
Sub-Campaign Code:	M49	Service Bulletin Number:	19-019		
Sub-Campaign Name:	2014-19 MDX Tailgate Inner Taillight Safety Recall	Sub-Campaign Superseded To:			
Sub-Campaign Type:	Safety, Stop Sale	Remedy Status:	Remedy Available		
Sub-Campaign Status:	Active	Dealer Active Date:	03/29/2019		
VEHICLE INFORMATION					
VIN Campaign Status	Campaign CLOSED	VIN Completion Date	10/12/2019		
Status Description	Fixed - Claim	Repair Order Date	10/11/2019		

JQ7: A/C Compressor Clutch Bolt		Active Date: 06/25/2015	Campaign CLOSED
CAMPAIGN INFORMATIO	N		
Campaign Name:	A/C COMPRESSOR CLUTCH BOLT	Campaign Type Description:	Recall
SUB-CAMPAIGN INFORM	ATION		
Sub-Campaign Code:	JQ7	Service Bulletin Number:	15-037
Sub-Campaign Name:	A/C Compressor Clutch Bolt	Sub-Campaign Superseded To:	
Sub-Campaign Type:		Remedy Status:	Remedy Available
Sub-Campaign Status:	Active	Dealer Active Date:	06/25/2015
VEHICLE INFORMATION			
VIN Campaign Status	Campaign CLOSED	VIN Completion Date	10/13/2015
Status Description	Fixed - Claim	Repair Order Date	

Repair Orders (10) **Customer RO Number: 395701** RO Open Date: 10/11/2019 **DEALER INFORMATION** Dealer ID: 251154 State: **CALIFORNIA** Name: **ACURA OF SERRAMONTE** Postal Code: 940143221 Address Line 1: 475 SERRAMONTE BLVD. Phone Number: 6509851000 Address Line 2: Status: Α City: **COLMA** REPAIR ORDER INFORMATION RO Num: **RO Close Date:** 395701 10/12/2019 Reference Num: 395701 Mileage In: 52079 RO Open Date: 10/11/2019 Mileage Out: 52079 Dealer Pay Jobs(1) JOB NUMBER: B JOB INFORMATION Operation ID: WASH **Operation Name:** PERFORM COURTESY EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS! **CODES AND COMMENTS** *Multi-Point InspectionVehicle Tire PresuresLF__RF__RR__LR_ Cause Desc: **Status Description: Complaint Code:** Correction Desc: 52079 PERFORMED MPI **CODES AND COMMENTS** PERFORM COURTESY Cause Desc: **Status Description:** EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS! Correction Desc: **Complaint Code:** Customer RO Number: 381645 RO Open Date: 11/02/2018 **DEALER INFORMATION** Dealer ID: 251154 State: **CALIFORNIA** Name: **ACURA OF SERRAMONTE** Postal Code: 940143221 Address Line 1: 475 SERRAMONTE BLVD. Phone Number: 6509851000 Address Line 2: Status: COLMA City: REPAIR ORDER INFORMATION RO Num: 381645 **RO Close Date:** 11/12/2018 Reference Num: 381645 Mileage In: 42204 RO Open Date: 11/02/2018 Mileage Out: 42205 Dealer Pay Jobs(1) JOB NUMBER: A **JOB INFORMATION** Operation ID: IAC Operation Name: PERFORM MULTI-POINT Inspection, vehicle TIRE **PRESSURES CODES AND COMMENTS**

Cause Desc: Status Description:

PROVIDE CUSTOMER WITH A NO CHARGE COURTSEY VEHICLE. CUSTOMER MUST NE 25 YEARS OF AGE; PROVIDE A VALID DRIVERS LICENSE; PROOF OF INSURANCE AND A

MAJOR CREDIT CARD. **Complaint Code:** Correction Desc:

CODES AND COMMENTS

Cause Desc: Status Description: PERFORM COURTESY

EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS!

Complaint Code: Correction Desc:

CODES AND COMMENTS

Status Description: PERFORM MULTI-POINT Cause Desc:

Inspection. vehicle TIRE PRESSURES

LF___RF_ RR

Complaint Code: Correction Desc: performed mpi

CODES AND COMMENTS

FAULTY SENSOR Status Description: Cause Desc:

CUSTOMER STATES WHEN ACCELRATE IN BETWEEN 2ND -3RD GEAR FELT A JOLT AND WHEN DOWN IT JERKS; AND ALL INDICTOR LIGHT ARE ON; CHECK AND ADVISE CUSTOMER TEXT ISSUE ON

DISPLAY TO ADVISOR. **Complaint Code: Correction Desc:** p0848 stored 3rd pressure switch.

rec replacement and recheck. replaced 3rd pressure switch; test drove vehicle for 10 miles; driving

as designed at this time OP;2321E3

CODES AND COMMENTS

Cause Desc: **Status Description:**

CUSTOMER STATES WHEN START UP VEHICLE AND SHIFT TO REVERSE AND NOTICE AUDIO AND NAVIGATION SCREEN IS BLANK; CHECK AND

ADVISE.

CALIFORNIA

Α

made several attempts; did not verify customer's concern at this Correction Desc: **Complaint Code:**

time. possible customer is not waiting for system to boot up fully before engaging reverse.

Customer RO Number: 379792 RO Open Date: 09/20/2018

DEALER INFORMATION

Dealer ID: 251154 State: **ACURA OF SERRAMONTE** Postal Code: Name:

940143221 Address Line 1: 475 SERRAMONTE BLVD. Phone Number: 6509851000

Address Line 2:

Status: City: **COLMA**

REPAIR ORDER INFORMATION

RO Num: 379792 **RO Close Date:** 09/21/2018 Reference Num: 379792 Mileage In: 41694 **RO Open Date:** 09/20/2018 Mileage Out: 41708

Customer Pay Jobs(1)

JOB NUMBER: B

JOB INFORMATION

Operation ID: DIAG **CUSTOMER STATES** Operation Name:

CODES AND COMMENTS

Cause Desc: TRANSMISSION WOULD LURCH **Status Description:** TRANSMISSION WOULD LURCH

FORWARD WHEN APPLYING

FORWARD WHEN APPLYING
GAS MOST NOTICABLE AT 2ND

TO 3RD GEAR. BEFORE THE LAST SERVICE ON 9-15-2018 ALMOST EVERYDAY TO OTHER DAY. AFTER THE TRANSMISSISION SOFTWARE

UPDATE AND THE

TRANSMISSION FLUID FLUSH. IN THE LAST 5 DAYS IT HAS HAPPEN ONCE MIDDAY AND DURING THE 2ND TO 3RD GEAR SHIFT THE CAR WOULD JERK FORWARD ABRUPTLY.

Correction Desc: 41708 PERFORMED ROAD TEST; **Complaint Code:**

COULDN'T DUPLICATE THE PROBLEM AT THIS TIME. CHECK TRANSMISSION FLUID LEVEL IS OKAY. CHECK FOR ANY DTC WITH THE HDS AND NONE WAS FOUND. RE-DO THE IDLE LEARN PROCEDURE AND ROAD TEST AGAIN WITH HDS AND TAKE SOME SNAP-SHOT AND REVIEW IT; THERE IS NO PROBLEM WITH THE TORQUE CONVERTER AT

THIS TIME. OP#218099

Dealer Pay Jobs(1)

JOB NUMBER: C

JOB INFORMATION

Operation ID: WASH Operation Name: PERFORM COURTESY

EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS!

CODES AND COMMENTS

PERFORM COURTESY Cause Desc: Status Description:

EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS!

Complaint Code: Correction Desc: 41708 SENT TO WASH.

LABOR INFORMATION

Labor Op ID: WASH Labor Op Code Desc: PERFORM COURTESY

EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS!

Labor Op Type: Qty:

Customer RO Number: 379394 RO Open Date: 09/12/2018

DEALER INFORMATION

Dealer ID: 251154 State: **CALIFORNIA** Name: ACURA OF SERRAMONTE Postal Code: 940143221 475 SERRAMONTE BLVD. Phone Number: 6509851000 Address Line 1:

Status:

Address Line 2:

City: **COLMA**

REPAIR ORDER INFORMATION

RO Num: 379394 **RO Close Date:** 09/15/2018 Reference Num: 379394 Mileage In: 41542 RO Open Date: 09/12/2018 Mileage Out: 41542

Dealer Pay Jobs(1)

JOB NUMBER: C

JOB INFORMATION

Operation ID: WASH Operation Name: PERFORM COURTESY

EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS!

CODES AND COMMENTS Cause Desc: **Status Description:** PERFORM MULTI-POINT Inspection, vehicle TIRE PRESSURES RF **Complaint Code:** Correction Desc: **CODES AND COMMENTS Status Description:** PERFORM COURTESY Cause Desc: EXTERIOR CAR WASH AND INTERIOR VACUUMING - THANK YOU FOR YOUR BUSINESS! **Complaint Code:** Correction Desc: 41542 **Customer RO Number: 362063** RO Open Date: 07/22/2017 **DEALER INFORMATION** Dealer ID: 251154 State: CALIFORNIA Name: **ACURA OF SERRAMONTE** Postal Code: 940143221 Address Line 1: 475 SERRAMONTE BLVD. Phone Number: 6509851000 Address Line 2: Status: Α City: **COLMA** REPAIR ORDER INFORMATION RO Num: **RO Close Date:** 362063 07/22/2017 Reference Num: 362063 Mileage In: 29845 **RO Open Date:** 07/22/2017 Mileage Out: 29845 Customer Pay Jobs(1) JOB NUMBER: A JOB INFORMATION Operation ID: ATF Operation Name: PERFORM AUTOMATIC TRANSMISSION FLUSH **CODES AND COMMENTS** PERFORM AUTOMATIC Cause Desc: Status Description: TRANSMISSION FLUSH **Complaint Code: Correction Desc: LABOR INFORMATION** Labor Op ID: Labor Op Code Desc: Labor Op Type: Qty: LABOR INFORMATION Labor Op ID: ATF Labor Op Code Desc: PERFORM AUTOMATIC TRANSMISSION FLUSH Labor Op Type: Qty: LABOR INFORMATION Labor Op ID: A/1S3B Labor Op Code Desc: MM3 REPLACE TRANSFER CASE OIL Labor Op Type: Qty: 1 PART INFORMATION Part Num: 90471-PX4-000 Part Qty: 1 Part Desc: WASHER; DRAIN (18MM) PART INFORMATION Part Num: 2 94109-20000 Part Qty: Part Desc: WASHER; DRAIN (20MM) PART INFORMATION Part Num: 90W Part Qty: 2 80/90WT GEAR OIL Part Desc: Dealer Pay Jobs(1)

JOB NUMBER: C JOB INFORMATION Operation ID: NIDB NO INTERVAL DUE BASIC **Operation Name: CODES AND COMMENTS** *No Interval Due *Vehicle History IndicatesNo Maintenance Interval Cause Desc: **Status Description: Complaint Code:** Correction Desc: **CODES AND COMMENTS** *Multi-Point InspectionVehicle Tire PresuresLF___RF___RR___LR__ Cause Desc: **Status Description: Complaint Code:** Correction Desc: PERFORMED MPI Warranty RO Number: 395701 RO Open Date: 10/11/2019 **DEALER INFORMATION CALIFORNIA** Dealer ID: 251154 State: **ACURA OF SERRAMONTE** Postal Code: 940143221 Address Line 1: 475 SERRAMONTE BLVD. **Phone Number:** 6509851000 Address Line 2: Status: City: **COLMA** REPAIR ORDER INFORMATION Repair Order Num: 395701 **RO Close Date:** 10/12/2019 **RO Open Date:** 10/11/2019 JOB NUMBER: 395701-W1 JOB INFORMATION INSPECTED BOTH TAIL GATE INNER TAIL LIGHTS NO WATER OR DAMAGE. INSTALLED HARNESS REPAIR KIT. **RECALL 19-019 Original Correction Desc: Original Cause Desc:** SAFETY RECALL CAMPAIGN: INSPECT. REPAIR BOTH LEFT AND RIGHT S/B: 19-019 **Original Complaint Desc: PART INFORMATION** Part Num: 06340-TZ5-A00 Part Qty: 1 Part Desc: REPAIR KIT, LID LIGHT Warranty RO Number: 381645 RO Open Date: 11/02/2018 **DEALER INFORMATION** Dealer ID: 251154 State: **CALIFORNIA** Name: **ACURA OF SERRAMONTE** Postal Code: 940143221 Address Line 1: 475 SERRAMONTE BLVD. **Phone Number:** 6509851000 Address Line 2: Status: City: **COLMA** REPAIR ORDER INFORMATION Repair Order Num: 381645 **RO Close Date:** 11/12/2018 11/02/2018 **RO Open Date:** JOB NUMBER: 381645-W1 JOB INFORMATION

Original Cause Desc: FAULTY SENSOR Original Correction Desc: P0848 STORED 3RD PRESSURE SWITCH. REC REPLACEMENT AND RECHECK. REPLACED 3RD PRESSURE SWITCH; TEST

PRESSURE SWITCH; TEST DROVE VEHICLE FOR 10 MILES; DRIVING AS DESIGNED AT THIS

TIME OP;2321E3

Original Complaint Desc: CUSTOMER STATES WHEN

ACCELRATE IN BETWEEN 2ND -3RD GEAR FELT A JOLT AND WHEN DOWN IT JERKS; AND ALL INDICTOR LIGHT ARE ON; CHECK AND ADVISE. CUSTOMER TEXT ISSUE ON DISPLAY TO ADVISOR.

PART INFORMATION

Part Num: 90471-PW7-A00 **Part Qty:** 1

Part Desc: GASKET (10MM)

PART INFORMATION

Part Num: 28600-R94-004 **Part Qty:** 1

Part Desc: SW, AT OIL PRESSURE

JOB NUMBER: 381645-W2

JOB INFORMATION

Original Cause Desc: CORROISION BUILD UP Original Correction Desc: 42205 REPLACED THROTTLE

42205 REPLACED THROTTLE BODY; TEST DROVE VEHICLE FOR 7 MILES; DRIVING AS DESIGNED AT THIS TIME OP:121165; PERFORMED IDLE LEARN AFTER REPAIRS

Original Complaint Desc: THROTTLE BODY - REPLACE.

S/B: 07-056

PART INFORMATION

Part Num: 16176-RYE-A10 **Part Qty:** 1

Part Desc: GSKT, THROTTLE BODY

PART INFORMATION

Part Num: 16400-R9P-A01 **Part Qty:** 1

Part Desc: THROTTLE BODY

Warranty RO Number: 379394 RO Open Date: 09/12/2018

DEALER INFORMATION

 Dealer ID:
 251154
 State:
 CALIFORNIA

 Name:
 ACURA OF SERRAMONTE
 Postal Code:
 940143221

 Address Line 1:
 475 SERRAMONTE BLVD.
 Phone Number:
 6509851000

Status:

Address Line 2:

City: COLMA

REPAIR ORDER INFORMATION

Repair Order Num: 379394 **RO Close Date:** 09/15/2018

RO Open Date: 09/12/2018

JOB NUMBER: 379394-W1

JOB INFORMATION

Original Cause Desc:

OCCASIONALLY VEH WILL

LURCH FORWARD WHEN IN

SECOND GEAR

TRANSMISSION WHEN IN DRIVE Original Correction Desc:

ON THE FIRST RUN OK 1ST GEAR SHIFT TO 2ND GEAR AND ALSO ON THE HIGHER GEAR SHIFT NORMAL ON THE SECOND ROAD TEST WITH THE OTHER TECHNICIAN FEEL NORMAL SHIFTING . CHECK THE ATF FLUID LEVEL OK AND CONDITION GOOD FOUND A/T PCM SOFTWARE NOT BEEN UPDATE YET. DURING AT PCM SOFTWARE UPDATED AND ATF FLUSH ROAD TEST AGAIN SHIFT STILL NORMAL OK AT THIS TIME. S/B 16-062 OC 1255E4 A . ROAD TEST ON THE OTHER DAY IN THE MORNING WITH THE SAME TECHNICIAN THE VEHICLE WAS IN COLD START AND DRIVE NORMAL SHIFT NORMAL.

41542 PERFORMED ROAD TEST

Original Complaint Desc:

CHECK ADVISE CUSTOMER
STATES THAT THE
TRANSMISSION SHIFTS
POORLY AT LOWER GEARS 12ND GEAR AND CUSTOMER
WOULD ALSO FEEL LIKE IT HAS
TROUBLE ACCELERATING THEN
WILL EVENTUALLY KICK INTO
THE NEXT GEAR. FEELS UNDER
POWERED AND THEN WILL
LIBCH FORWARD, CHECK AND LURCH FORWARD. CHECK AND

REPORT ISSUE.

PART INFORMATION

Part Num: 90471-PX4-000 Part Qty:

Part Desc: WASHER, DRAIN (18MM)

PART INFORMATION

Part Num: 90441-PK4-000 Part Qty:

Part Desc: WASHER (24MM)

PART INFORMATION

Part Num: 08200-9008A Part Qty: 10

Part Desc: FLUID (ATF DW-1)

RO Open Date: 10/13/2015 Warranty RO Number: 332707

DEALER INFORMATION

Dealer ID: 251154 State: **CALIFORNIA ACURA OF SERRAMONTE** Name: Postal Code: 940143221 6509851000 Address Line 1: 475 SERRAMONTE BLVD. Phone Number:

Address Line 2:

Status:

City: **COLMA**

REPAIR ORDER INFORMATION

Repair Order Num: 332707 **RO Close Date:** 10/14/2015

RO Open Date: 10/13/2015

JOB NUMBER: 332707-W1

JOB INFORMATION

10773 INSTALLED SOP PARTS DRIVER'S SIDE WINDSHIELD MOLDINGS / Original Cause Desc: **DEFORMED MOLDING Original Correction Desc:**

CUSTOMER STATES THAT MOLDING ON WINDSHIELD HAS A DEFECT SOP PARTS HAVE BEEN ORDERED PLEASE REPLACE MOLDING

PART INFORMATION

Original Complaint Desc:

Part Num: 73162-TZ5-A01 Part Qty: 1

Part Desc: GARNISH, L. FR.

PART INFORMATION

Part Num: 08713-0008B Part Qty: 1

Part Desc: NOT FOUND

Warranty RO Number: 332564 RO Open Date: 10/09/2015

DEALER INFORMATION

Dealer ID: 251154 **CALIFORNIA** State: Name: ACURA OF SERRAMONTE Postal Code: 940143221

475 SERRAMONTE BLVD. 6509851000 Address Line 1: **Phone Number:**

Address Line 2: Status:

City: COLMA

REPAIR ORDER INFORMATION

332564 **RO Close Date:** 10/10/2015 Repair Order Num:

RO Open Date: 10/09/2015

JOB NUMBER: 332564-W1

JOB INFORMATION

10607 REPLACED A/C BOLT AS PER RECALL 15-037 **Original Cause Desc:** W Original Correction Desc:

Original Complaint Desc: A/C BOLT RECALL

PART INFORMATION

Part Num: 38823-5J6-A11 Part Qty: 1

Part Desc: BOLT SET (M6)

Vehicle Production (1)

Assembly Frame Off Date: 08/21/2014 VIN: 5FRYD4H26FB010884

FACTORY MODEL INFORMATION

HONDA MANUFACTURING OF ALABAMA Factory Name: **Factory Paint Color Name:** ALABASTER SILVER METALLIC

Factory Paint Color Code: NH-700M

VEHICLE COMPONENT INFORMATION

Transmission Serial Num: PJ8A2012270 **Block Cast Serial Num:**

Engine Serial Num: J35Y52016725

MANUFACTURING INFORMATION

Assembly Frame Off Time: 08/21/2014

SPECIAL MODEL FEATURES

Special Model Feature Cd	Special Model Feature Name
АНА	AHA Radio
втитн	Bluetooth
PNDRA	Pandora
XMRDO	XM Radio

Feature Name	Feature Value
100	
ABS AC	Y
BATTERY CCA OEM	610
BATTERY CCA SERVICE	630
BLIND SPOT INFO	N
BRAKES REAR DISC	Y
CD CHANGER	N
CD PLAYER	Y
CMBS	N
CRUISE CONTROL	Y
DESIGN TEAM	HRAO
DOORS	5
EMISSIONS LEVEL	ULEV2
ENGINE CYLINDERS	6
ENGINE DISPLACEMENT	3.5L
ENGINE HP	290
ENGINE PREFIX	J35Y5
ENGINE SERIES	NP0
FOG LIGHTS	Υ
FOUR WHEEL DRIVE	Υ
GRADE LONG	BASE
GRADE SHORT	BASE
HANDSFREELINK	Υ
HIP	
HOMELINK	Υ
HVAC FRONT AUTO	Υ
HVAC MODE QUANTITY	
HVAC ZONE QUANTITY	
MIRRORS HEATED	Υ
MODEL GENERATION	14G
MTO DETAIL	MDX 14G HMA
NAMEPLATE	ACURA
NAVIGATION	N
PARKING SENSORS	N
POWER DOOR LOCK	Y
POWER SLIDING DOOR	N
POWER TAILGATE	Y
POWER TYPE	GASOLINE
POWER WINDOWS	Y
REAR CAMERA	Y
REAR SPOILER	Y
REMOTE ENTRY	Y
RES	N N
ROOF RACK	N N
RUN FLAT TIRE	N Y
SATELLITE RADIO	Y
SEAT DRIVER HEIGHT SEAT DRIVER LUMBAR	N POWER
SEAT DRIVER POWER SEAT MEMORY	10-WAY Y
SEAT MEMORY SEAT PASSENGER POWER	8-WAY
SEAT PASSENGER POWER SEATS HEATED	Y
SEATS LEATED SEATS LEATHER	Y
SECURITY SYSTEM	Y
SECURITY SYSTEM SH AWD	Y
SRS CURTAIN	Y
SRS FRONT SIDE	Y
STABILITY ASSIST	VSA
SUNROOF	Y

TEST		
TIRE SIZE	245/60R18 105H	
TPMS	Υ	
TRANSMISSION	A/T	
TRANSMISSION GEARS	6	
TRANSMISSION PREFIX		
TRANSMISSION SERIES	6AT	
VCM ENGINE	Υ	
VIN STRUCTURE	5FRYD4H2?FB	
WHEELS ALLOY	Υ	

Vehicle Sale (1)

VIN: 5FRYD4H26FB010884 Retail Sales Date: 09/23/2014

SALES MODEL INFORMATION

YD4H2FJNW Sales Ext Paint: ALABASTER SILVER METALLIC Sales Model Code:

Sales Ext Color Code: SA Sales Int Color Code: ΕN Sales Ext Color Name: SILVER Sales Int Color Name: **EBONY**

SALES INFORMATION

Sales Date: 09/23/2014 Warranty Registration Date: 09/23/2014

In Service Date: 09/23/2014 Vehicle Service Contract Flag:

RETAIL DEALER INFORMATION

Name: **ACURA OF SERRAMONTE** State: **CALIFORNIA**

Address Line 1: Postal Code: 94014 475 SERRAMONTE BLVD. Address Line 2: Country: U.S.A. City: **COLMA** Phone Number: 6509851000

PRE DELIVERY INSPECTION DEALER INFORMATION

Name: **ACURA OF SERRAMONTE** State: **CALIFORNIA** Address Line 1: 475 SERRAMONTE BLVD. **Postal Code:** 94014 Address Line 2: Country: U.S.A.

City: **COLMA** Phone Number: 6509851000

Warranty Claims (12)

APPROVED CLAIMS (6)

Dealer ID: 251154 Defect Code: 6LL00 Primary Labor Code: 7140B0

Claim Paid Date: 10/12/2019 Claim Number: 957011 Failed Part Number: 34150-TZ5-H02

DEALER INFORMATION

Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000

CLAIM INFORMATION

Claim Num: 957011 RO Num: 395701 Claim Received Date: 10/12/2019 RO Year: 2019

Claim Paid Date: 10/12/2019

APPROVED CLAIM INFORMATION

Defect Code: 52079 6LL00 Mileage:

Defect Code Desc: MDX TAILGATE LID LIGHT

ELECTRICAL SHORT

FAILED PART INFORMATION

Part Num: 34150-TZ5-H02 Part Desc: LIGHT ASSY., R. LID **REPLACED PARTS (1)**

PART INFORMATION

Part Num: 06340-TZ5-A00 Part Qty: 1

Part Desc: REPAIR KIT,LID LIGHT

LABOR OPERATION CODES (1)

LABOR OP INFORMATION

Labor Op Code: 7140B0 Labor Op Desc:

SAFETY RECALL CAMPAIGN: INSPECT. REPAIR BOTH LEFT AND RIGHT INNER TAILLIGHT. INSTALL HARNESS (REPAIR

Primary Labor Code: 223507/222134 Dealer ID: 251154 Defect Code: 03214

Claim Paid Date: 01/22/2019

Claim Number: 816452 Failed Part Number: 28600-R94-004

DEALER INFORMATION

Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000

CLAIM INFORMATION

RO Num: Claim Num: 816452 381645 Claim Received Date: RO Year: 2018 01/22/2019

Claim Paid Date: 01/22/2019

APPROVED CLAIM INFORMATION

Defect Code: Mileage: 42204

Defect Code Desc: **ERRONEOUS OPERATION**

FAILED PART INFORMATION

Part Desc: SW, AT OIL PRESSURE Part Num: 28600-R94-004

DIAGNOSTIC TROUBLE CODES (2)

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

REPLACED PARTS (2)

PART INFORMATION

Part Num: 28600-R94-004 Part Qty: 1

Part Desc: SW, AT OIL PRESSURE

PART INFORMATION

Part Num: 90471-PW7-A00 Part Qty: 1

Part Desc: GASKET (10MM)

LABOR OPERATION CODES (2)

LABOR OP INFORMATION

Labor Op Code: 223507 Labor Op Desc:

DIAGNOSTIC TROUBLE CODE / TRANSMISSION - Retrieve codes with the HDS, read data,

troubleshoot, and c

LABOR OP INFORMATION

Labor Op Code: 222134 Labor Op Desc: **AUTOMATIC TRANSMISSION**

PRESSURE SWITCH "A" -

REPLACE.

Dealer ID: 251154 Defect Code: 03001 Primary Labor Code: 121165

Claim Number: 816456 Failed Part Number: 16400-R9P-A01 Claim Paid Date: 11/15/2018

DEALER INFORMATION

Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000

CLAIM INFORMATION

Claim Num: 816456 RO Num: 381645 Claim Received Date: 11/15/2018 **RO Year:** 2018

Claim Paid Date: 11/15/2018

APPROVED CLAIM INFORMATION

Defect Code: Mileage: 42204

Defect Code Desc: BINDING/STICKING

FAILED PART INFORMATION

Part Num: 16400-R9P-A01 Part Desc: THROTTLE BODY

DIAGNOSTIC TROUBLE CODES (2)

DTC INFORMATION

Code: P2101 THROTTLE ACTUATOR SYSTEM Code Desc:

MALFUNCTION

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

REPLACED PARTS (2) PART INFORMATION Part Num: 16176-RYE-A10 Part Qty: 1 Part Desc: GSKT, THROTTLE BODY PART INFORMATION Part Num: 16400-R9P-A01 Part Qty: 1 Part Desc: THROTTLE BODY **LABOR OPERATION CODES (1)** LABOR OP INFORMATION Labor Op Code: 121165 Labor Op Desc: THROTTLE BODY - Replace. Primary Labor Code: 1255E4/1255E4A Dealer ID: 251154 Defect Code: 03214 Claim Number: 793942 Failed Part Number: 37805-5J6-3050 Claim Paid Date: 09/15/2018 **DEALER INFORMATION** Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000 **CLAIM INFORMATION** Claim Num: 793942 **RO Num:** 379394 **Claim Received Date:** 09/15/2018 **RO Year:** 2018 Claim Paid Date: 09/15/2018 APPROVED CLAIM INFORMATION **Defect Code:** Mileage: 41542 **Defect Code Desc: ERRONEOUS OPERATION FAILED PART INFORMATION** Part Num: 37805-5J6-3050 Part Desc: **SOFTWARE REPLACED PARTS (3)** PART INFORMATION Part Num: 90441-PK4-000 Part Qty: 1 Part Desc: WASHER (24MM) PART INFORMATION 08200-9008A Part Num: Part Qty: 10 FLUID (ATF DW-1) Part Desc: PART INFORMATION Part Num: 90471-PX4-000 Part Qty: 1 Part Desc: WASHER, DRAIN (18MM) **LABOR OPERATION CODES (2)** LABOR OP INFORMATION Labor Op Code: 1255E4 Labor Op Desc: UPDATE THE 6A/T SOFTWARE (JUDDER) LABOR OP INFORMATION

Labor Op Desc:

Labor Op Code:

1255E4A

FLUSH THE ATF (first visit)

Dealer ID: 251154 Defect Code: 03214 Primary Labor Code: 8481B2

Claim Number: 327071 Failed Part Number: 73162-TZ5-A01 Claim Paid Date: 10/15/2015

DEALER INFORMATION

ACURA OF SERRAMONTE Phone Number: 6509851000 Name:

CLAIM INFORMATION

Claim Num: 327071 RO Num: 332707 Claim Received Date: 10/14/2015 **RO Year:** 2015

Claim Paid Date: 10/15/2015

APPROVED CLAIM INFORMATION

Defect Code: 03214 Mileage: 10773

Defect Code Desc: ERRONEOUS OPERATION

FAILED PART INFORMATION

Part Num: Part Desc: GARNISH, L. FR. 73162-TZ5-A01

LABOR OPERATION CODES (1)

LABOR OP INFORMATION

GARNISH, FRONT WINDSHIELD Labor Op Code: 8481B2 Labor Op Desc:

SIDE LEFT

Dealer ID: 251154 **Defect Code: 5ZU00** Primary Labor Code: 6141D0

Claim Paid Date: 10/12/2015 Claim Number: 325641 Failed Part Number: 38810-5J6-A02

DEALER INFORMATION

Name: **ACURA OF SERRAMONTE** Phone Number: 6509851000

CLAIM INFORMATION

RO Num: Claim Num: 325641 332564 **Claim Received Date: RO Year:** 2015 10/12/2015

Claim Paid Date: 10/12/2015

APPROVED CLAIM INFORMATION

Mileage: **Defect Code:** 5ZU00 10607

Defect Code Desc: A/C COMPRESSOR CLUTCH

FAILED PART INFORMATION

Part Num: 38810-5J6-A02 Part Desc: COMPRESSOR

LABOR OPERATION CODES (1)

LABOR OP INFORMATION

SAFETY RECALL CAMPAIGN: AC COMPRESSOR CLUTCH BOLT-REPLACE Labor Op Code: 6141D0 Labor Op Desc:

SUBMITTED CLAIMS (6)

Claim Received Date: 10/12/2019 Claim Number: 957011

DEALER INFORMATION

ACURA OF SERRAMONTE Phone Number: 6509851000 Name:

CLAIM INFORMATION

Claim Num: 957011 RO Num: 395701 Claim Received Date: 10/12/2019 RO Year: 2019

REPLACED PARTS (1)

PART INFORMATION

Part Qty: Part Num: 06340-TZ5-A00 1

Part Desc: REPAIR KIT, LID LIGHT

LABOR OPERATION CODES (1)

LABOR OP INFORMATION

Labor Op Code: 7140B0 Labor Op Desc:

SAFETY RECALL CAMPAIGN: INSPECT. REPAIR BOTH LEFT AND RIGHT INNER TAILLIGHT. INSTALL HARNESS (REPAIR

Claim Number: 816452 Claim Received Date: 01/22/2019

DEALER INFORMATION

Name: ACURA OF SERRAMONTE 6509851000 **Phone Number:**

CLAIM INFORMATION

Claim Num: 816452 **RO Num:** 381645 **Claim Received Date:** 01/22/2019 **RO Year:** 2018

DIAGNOSTIC TROUBLE CODES (2)

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

REPLACED PARTS (2)

PART INFORMATION

Part Num: 28600-R94-004 Part Qty: 1

Part Desc: SW, AT OIL PRESSURE

PART INFORMATION

Part Num: 90471-PW7-A00 Part Qty: 1

Part Desc: GASKET (10MM)

LABOR OPERATION CODES (2)

LABOR OP INFORMATION

Labor Op Code: 223507 Labor Op Desc:

DIAGNOSTIC TROUBLE CODE / TRANSMISSION - Retrieve codes with the HDS, read data,

troubleshoot, and c

LABOR OP INFORMATION

AUTOMATIC TRANSMISSION PRESSURE SWITCH "A" -Labor Op Code: 222134 Labor Op Desc:

REPLACE.

Claim Number: 816456 Claim Received Date: 11/15/2018

DEALER INFORMATION

Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000

CLAIM INFORMATION

Claim Num: 816456 RO Num: 381645 Claim Received Date: 11/15/2018 **RO Year:** 2018

DIAGNOSTIC TROUBLE CODES (2)

DTC INFORMATION

Code: P2101 Code Desc: THROTTLE ACTUATOR SYSTEM

MALFUNCTION

DTC INFORMATION

Code: P0848 Code Desc:

TRANSMISSION FLUID PRESSURE SENSOR/SWITCH "B" CIRCUIT HIGH

REPLACED PARTS (2)

PART INFORMATION

Part Qty: Part Num: 16176-RYE-A10

Part Desc: GSKT, THROTTLE BODY

PART INFORMATION

Part Num: 16400-R9P-A01 Part Qty: 1

Part Desc: THROTTLE BODY

LABOR OPERATION CODES (1)

LABOR OP INFORMATION

Labor Op Code: 121165 Labor Op Desc: THROTTLE BODY - Replace.

Claim Number: 793942 Claim Received Date: 09/15/2018 **DEALER INFORMATION** ACURA OF SERRAMONTE Name: **Phone Number:** 6509851000 **CLAIM INFORMATION** RO Num: Claim Num: 793942 379394 Claim Received Date: 09/15/2018 **RO Year:** 2018 REPLACED PARTS (3) PART INFORMATION Part Qty: Part Num: 90441-PK4-000 1 Part Desc: WASHER (24MM) **PART INFORMATION** Part Num: 08200-9008A Part Qty: 10 Part Desc: FLUID (ATF DW-1) **PART INFORMATION** Part Num: 90471-PX4-000 Part Qty: 1 Part Desc: WASHER, DRAIN (18MM) **LABOR OPERATION CODES (2)** LABOR OP INFORMATION UPDATE THE 6A/T SOFTWARE Labor Op Code: 1255E4 Labor Op Desc: (JUDDER) **LABOR OP INFORMATION** Labor Op Desc: Labor Op Code: 1255E4A FLUSH THE ATF (first visit) Claim Number: 327071 Claim Received Date: 10/14/2015 **DEALER INFORMATION** Name: **ACURA OF SERRAMONTE Phone Number:** 6509851000 **CLAIM INFORMATION** RO Num: Claim Num: 327071 332707 RO Year: Claim Received Date: 10/14/2015 2015 **LABOR OPERATION CODES (1)** LABOR OP INFORMATION GARNISH, FRONT WINDSHIELD Labor Op Code: 8481B2 Labor Op Desc: SIDE LEFT Claim Received Date: 10/12/2015 Claim Number: 325641 **DEALER INFORMATION** ACURA OF SERRAMONTE **Phone Number:** 6509851000 Name: **CLAIM INFORMATION** Claim Num: 325641 RO Num: 332564 Claim Received Date: 10/12/2015 **RO Year:** 2015

LABOR OPERATION CODES (1)

LABOR OP INFORMATION
Labor Op Code: 6141D0 Labor Op Desc: SAFETY RECALL CAMPAIGN: AC COMPRESSOR CLUTCH BOLT-REPLACE