

STATUS	PRODUCT INFORMATION	EVENT LOG	ADDRESSES	CONFIGURATION	HELP
--------	---------------------	-----------	-----------	---------------	------

## Event Log

The table below contains the log of events that the SB6190 has detected. This log can be important to the service provider to help diagnose and correct problems, if any should occur.

Time	Priority	Description
Wed Mar 22 12:52:57 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 12:52:58 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 12:53:13 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 12:53:17 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:01:27 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:02:52 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:02:57 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:03:09 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:03:11 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:03:18 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:15:06 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:25:36 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:30:32 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:30:49 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:32:52 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:37:28 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:43:49 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 13:44:49 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 14:03:12 2017	3	SYNC Timing Synchronization failure - Loss of Sync;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;
Wed Mar 22 14:03:17 2017	5	RCS Partial Service;CM-MAC=2c:7e:81:2a:f8:89;CMTS-MAC=00:14:f1:eb:b1:79;CM-QOS=1.1;CM-VER=3.0;

[STATUS](#)[PRODUCT  
INFORMATION](#)[EVENT LOG](#)[ADDRESSES](#)[CONFIGURATION](#)[HELP](#)

© 2015 ARRIS Group, Inc. ALL RIGHTS RESERVED.